


JDA0002(Corolla-2S)

# Electric Wiring Diagram

MADE IN CHINA



220~240V AC


KA POWER SWITCH  
M1 COMPRESSOR  
M3,4 STIRRING MOTOR

KT THERMOSTAT  
K1,2 SWITCH OF STIRRING/SPRAYING MOTOR  
M2,5 CONDENSATOR MOTOR FAN

JDA0001(Corolla-1S)

# Electric Wiring Diagram

MADE IN CHINA



220~240V AC

KA POWER SWITCH

M1 COMPRESSOR

M3 STIRRING MOTOR

KT THERMOSTAT

K1 SWITCH OF STIRRING/SPRAYING MOTOR

M2 CONDENSATOR MOTOR FAN